# **Araldite<sup>®</sup> Casting Resin System**

Araldite <sup>®</sup> CW 2245	Resin	100	pbv	100	pbw
Aradur <sup>®</sup> HY 177	Hardener	26	pbv	16	pbw
Aradur <sup>®</sup> HY 226	Hardener	19	pbv	12	pbw
Hardener LC 234	Hardener	16	pbv	10	pbw
Aradur <sup>®</sup> 943	Hardener	12	pbv	8	pbw

Flame retardant, epoxy based casting system for processing and curing at room temperature or slightly higher temperatures.

Application	Transformers, filters, capacitors etc.	
Processing methods	Casting / Impregnating. Manually or with automatic mixing and dosing equipment.	
Key Properties	Low shrinkage on curing Good thermal conductivity Good temperature and shock resistance	
	Flame retardant *Tested to AS 2431–1981 – Electrical equipment for explosive atmospheres – report available	

# Product Data (Guideline Values)

### Araldite<sup>®</sup> CW 2245 CI

Modified epoxy resin, containing mineral filler

Viscosity	at 25°C	mPa.s	18000 - 26000
Specific Gravity	at 25°C		1.65
Flash Point	°C		190 - 200
As Supplied Form	White high visc	osity filled liquid	
Hazardous Decomposition Products	Carbon monox vapours if bur	xide, carbon dioxide ned.	and other toxic gases and
Disposal	Regular proced	lures approved by nation	nal and/or local authorities.

### Aradur<sup>®</sup> HY 177 CI

Hardener				
Viscosity	at 25°C	mPa.s	700 - 1000	
Specific Gravity	at 25°C		0.95 – 1.0	
Flash Point	°C		> 160	
As Supplied Form	Clear amber liqu	uid		

## Aradur<sup>®</sup> HY 226 CI

Hardener				
Viscosity	at 25°C	mPa.s	600 - 1100	
Specific Gravity	at 25°C		0.96 – 1.01	
Flash Point	°C		> 100	
As Supplied Form	Clear pale yello	w liquid		

# Hardener LC 234

Hardener				
Viscosity	at 25°C	mPa.s	700 - 1200	
Specific Gravity	at 25°C		1.0 – 1.05	
Flash point	°C		> 100	
As supplied form	Clear pale yello	w liquid		

#### Aradur 943

Hardener			
Viscosity	at 25°C	mPa.s	3400 - 5000
Specific Gravity	at 25°C		1.07
Flash Point	°C		> 110
As Supplied Form	Clear pale yellow liqui	d	
Hazardous decomposition products	Carbon monoxide, c vapours if burned	arbon dioxide and ot	her toxic gases and
Disposal	Regular procedures a	oproved by nation and/or	r local authorities.

### **Processing Data (Guideline Values)**

Property	Araldite CW 2245 CI Aradur HY 177 CI	Araldite CW 2245 CI Aradur HY 226 CI	Araldite CW 2245 CI Hardener LC 234	Araldite CW 2245 CI Aradur 943
Mix Ratio	100 : 16 pbw 100 : 26 pbv	100 : 12 pbw 100 : 19 pbv	100 : 10 pbw 100 : 16 pbv	100 : 8 pbw 100 : 12 pbv
Gel time at 25°C	154 minutes	138 minutes	117 minutes	42 minutes
Pot life at 25°C	115 minutes	105 minutes	85 minutes	30 minutes
Gel time at 60°C	36 minutes	34 minutes	24 minutes	10 minutes
Initial Mix density	1.47	1.51	1.52	1.54
Initial Mix viscosity (mPa.s)	11,600	8,160	11,440	12,560
Peak exotherm	60°C after	50°C after	70°C after	115°C after
(500 ml casting)	2 hours	2 hours 20 mins	2 hours	45 minutes

### **Processing and Storage (Guideline Values)**

#### Mixing

Araldite<sup>®</sup> CW 2245 contains fillers which tend to settle over time. It is therefore recommended to carefully homogenize the complete contents of the container before use.

In the storage vessels of the production equipment, the pre filled products should be stirred up from time to time to avoid sedimentation and irregular metering.

#### Curing

To determine whether cross-linking has been carried to completion and the final properties are optimal, it is necessary to carry out relevant measurements on the actual object or to measure the glass transition temperature. Different gel and cure cycles in the customer's manufacturing process could lead to a different degree of cross-linking and thus a different glass transition temperature.

#### **Storage Conditions**

Store the components in a dry place at 18-25°C, in tightly sealed original containers. Under these conditions, the shelf life will correspond to the expiry date stated on the label. After this date, the product may be processed only after reanalysis. Partly emptied containers should be tightly closed immediately after use.

For information on waste disposal and hazardous products of decomposition in the event of a fire, refer to the Material Safety Data Sheets (MSDS) for these particular products.

#### Conversion to S1 – units

1 mPa.s	=	1 cP	
1 N/mm <sup>2</sup>	=	10kp/cm <sup>2</sup>	
1 W(m.k)	=	0.86 kcal	/mh⁰ C
1 K <sup>-1</sup>	=	1/K	1mm/mmºC

## **Mechanical and Physical Properties (Guideline Values)**

Property	Araldite CW 2245 CI Aradur HY 177	Araldite CW 2245 CI Aradur HY 226	Araldite CW 2245 CI Hardener LC 234	Araldite CW 2245 CI Aradur 943
Shore D after 24 hours at 25 $^\circ\text{C}$	73	85	90	90
Shore D after 6 hours at 60 °C	83	90	95	90
Tg (°C)	51	48	70	74
Water absorption (after 10 days immersion)	0.5 % w/w	0.2 % w/w	0.2 % w/w	0.2 % w/w
Tensile strength (MPa) -ISO 527/95	25.2	30.6	32.8	34.1
Elongation at break (%)	2.4	1.2	1.0	0.9
Coefficient of linear expansion (1x10 <sup>-6</sup> K <sup>-1</sup> ) - DIN 53752/80	84.3	67.4	64.8	53.2
Thermal Conductivity W/mK	0.6-0.65	0.6-0.65	0.6-0.65	0.6-0.65

Determined on standard test specimen at 25°C. Cured for 7 days at 22° C

### Industrial hygiene

Mandatory and recommended industrial hygiene procedures should be followed whenever our products are being handled and processed. For additional information please consult the corresponding Safety Data Sheets and the brochure "Hygienic precautions for handling plastics products".

#### **Handling Precautions**

Safety precautions at workplace: protective clothing gloves arm protectors goggles/safety glasses respirator/dust mask	Yes. Essential. Recommended when skin contact likely. Yes. Recommended.
Skin protection: before starting work after washing	Apply barrier cream to exposed skin. Apply barrier or nourishing cream.
Cleaning of contaminated skin	Dab off with absorbent paper, wash with warm water and alkali-free soap, then dry with disposable towels. Do not use solvents.
Clean shop requirements	Cover workbenches, etc. with light coloured paper. Use disposable beakers, etc.
Disposal of spillage	Soak up with sawdust or cotton waste and
Ventilation: of workshop of workplace	deposit in plastic-lined bin. Renew air 3 to 5 times an hour. Exhaust fans. Operatives should avoid inhaling vapors.

#### **First Aid**

Contamination of the **eyes** by resin, hardener or casting mix should be treated immediately by flushing with clean, running water for 10 to 15 minutes. A doctor should then be consulted.

Material smeared or splashed on the **skin** should be dabbed off, and the contaminated area then washed and treated with a cleansing cream (see above). A doctor should be consulted in the event of severe irritation or burns. Contaminated clothing should be changed immediately.

For more detailed information please read Huntsman Advanced Material safety data sheets for the individual products.

#### Note

Araldite<sup>®</sup> is a registered trademark of Huntsman Corporation or an affiliate thereof in one or more countries, but not all countries.

Huntsman Corporation <sup>®</sup>Registered trademark



All recommendations for use of our products, whether given by us in writing, verbally, or to be implied from results of tests carried out by us are based on the current state of our knowledge. Notwithstanding any such recommendations the Buyer shall remain responsible for satisfying himself that the products as supplied by us are suitable for his intended process or purpose. Since we cannot control the application, use or processing of the products, we cannot accept responsibility therefore. The Buyer shall ensure that the intended use of the products will not infringe any third party's intellectual property rights. We warrant that our products are free from defects in accordance with and subject to our general conditions of supply.

Huntsman Advanced Materials (Australia) Pty Limited ABN 93 091 627 879 Gate 3 Ballarat Road, Deer Park, VIC Tel: + 61 3 9361 6060 Fax: +61 3 9361 6066 http://www.huntsman.com