

#### **Gelcoat Resin**

# RenGel<sup>®</sup> SW 10 / Ren<sup>®</sup> HY 2404 or HY 5159

### Polishable and pigmentable epoxy system

#### **Key properties**

- Easily machinable ( soft fillers )
- Polishable
- Low odour

#### **Applications**

- · Negatives, moulds and fixtures
- Pattern / tools for the ceramic industry (plaster working moulds)

#### **Product data**

Property	Unit	RenGel SW 10	Ren HY 2404	Ren HY 5159
Appearance Colour	visual	Paste White	Clear liquid Pale yellow	Clear liquid Pale yellow
Viscosity at 25°C	mPas	Thixotropic	3,500-5,500	150-250
Density	g/cm <sup>3</sup>	1.54	1.0-1.05	0.98

#### **Processing**

Mix ratio	Parts by weight		
RenGel SW 10	100	100	
Ren HY 2404	10	-	
Ren HY 5159	-	8	

Mix the two components thoroughly in the ratio indicated.

Apply in thin layers with a brush or spatula, wait until gelcoat has gelled, but ensure that it is still slightly tacky before proceeding.

Post-curing will improve final properties.

#### **Properties**

Resin/Hardener mix:	Volume	Unit	SW 10 HY 2404	SW 10 HY 5159
Appearance			White	White
Pot life at 25°C	250 ml	min	20	60
Demoulding time		h	12	12

After cure: with HY 2404: 7 days at RT / 14 hours at 40°C with HY 5159: 14 hours at 60°C

Density	ISO 1183	g/cm <sup>3</sup>	1.5	1.5
Hardness	ISO 868	Shore D	85-90	85-90
Deflection temperature	ISO 75	°C	60-70	80
Abrasion	Taber	mm <sup>3</sup> /100U	100-110	100-110

#### **Storage**

The resin and hardeners described in this instruction sheet have the shelf lives shown provided they are stored at 6 - 28 °C in a dry place and sealed containers, preferably those in which they are supplied.

### Working condition

The products should be handled when in the temperature range of 20 - 25°C.

#### **Packaging**

System	SW 10	HY 2404	HY 5159
Quantity and Weight	4 x 3kg	6 x 300gr	6 x 240gr
Quantity and Weight	12 x 300gr	6 x 30gr	6 x 24gr

## Handling precautions

#### Caution

Our products are generally quite harmless to handle provided that certain precautions normally taken when handling chemicals are observed. The uncured materials must not, for instance, be allowed to come into contact with foodstuffs or food utensils, and measures should be taken to prevent the uncured materials from coming in contact with the skin, since people with particularly sensitive skin may be affected. The wearing of impervious rubber or plastic gloves will normally be necessary; likewise the use of eye protection. The skin should be thoroughly cleansed at the end of each working period by washing with soap and warm water. The use of solvents is to be avoided. Disposable paper - not cloth towels - should be used to dry the skin. Adequate ventilation of the working area is recommended. These precautions are described in greater detail in the Material Safety Data sheets for the individual products and should be referred to for fuller information.

#### Huntsman Advanced Materials (UK) Limited

All recommendations for the use of our products, whether given by us in writing, verbally, or to be implied from the results of tests carried out by us, are based on the current state of our knowledge. Notwithstanding any such recommendations the Buyer shall remain responsible for satisfying himself that the products as supplied by us are suitable for his intended process or purpose. Since we cannot control the application, use or processing of the products, we cannot accept responsibility therefore. The Buyer shall ensure that the intended use of the products will not infringe any third party's intellectual property rights. We warrant that our products are free from defects in accordance with and subject to our general conditions of supply.

Duxford, Cambridge England CB2 4QA

Tel: +44 (0) 1223 493 000 Fax: +44 (0) 1223 493 002

www.renshape.com

© 2004 Huntsman Advanced Materials (Switzerland) GmbH

® Ren, RenShape, RenPaste, RenGel, RenLam, RenCast, RenLease, RenPIM and Parts In Minutes are registered trademarks of Huntsman LLC or an affiliate thereof in one or more, but not all, countries.